40 C

Discipline: FIRE

Zone: MIC? see email

Inspector:

Scheduled On: 10/03/2017

Permit Number: P17-100634 **IVR Number:** 0002 **Passed** / **Failed:** Fail

Inspection Type: FIRE SPRINKLER/STANDPIPE FINAL **Application Type:** CONTRACTOR

Permit Type: FIRE SPRINKLER SYSTEM

Folio Number: 514213020010 **Job Address:** 101 N OCEAN DR **Floor:** 1

Legal Description:

Relationship	Name	Phone	Phone 2
FIRE SPRINKLERS	ALL FIRE SERVICES INC	954-653-1142	954-367-3607
OWNER			

Date	User	Comment
08/23/2017	RLONG	HOLLYWOOD BEACH RESORT CONDO Reconnection of the Fire Alarm System to the replaced flow switches is under the the Fire Alarm System permit E17-101977 --- Fire Sprinkler repairs under permit numbers P17-100634 P17-100444 ---
08/31/2017	mhofleb	Tested 4 tampers on new control valves on this date. This permit still show CA for Fire Alarm shop drawings. Fire Alarm drawings were submitted under another Fire Alarm permit that has a different scope E17-101977.
09/28/2017	mhofleb	Only need to check that all penetrations in Fire Pump room are sealed and axillary drain sign is in place. Tampers for control valves for this new line were tested-OK they are on E17-101977.

Ed 786-562-0165

Schaffer 786-402-9849

Discipline: FIRE

Zone:

Inspector:

Scheduled On: 10/03/2017

Permit Number: P17-100444 **IVR Number:** 0002 **Passed** **Failed:** Full

Inspection Type: FIRE SPRINKLER/STANDPIPE FINAL **Application Type:** CONTRACTOR

Permit Type: FIRE SPRINKLER SYSTEM

Folio Number: 514213020010 **Job Address:** 101 N OCEAN DR **Floor:** 1

Legal Description:

Relationship	Name	Phone	Phone 2
FIRE SPRINKLERS	ALL FIRE SERVICES INC	954-653-1142	954-367-3607
OWNER			

Date	User	Comment
08/23/2017	RLONG	HOLLYWOOD BEACH RESORT CONDO Reconnection of the Fire Alarm System to the replaced flow switches is under the the Fire Alarm System permit E17-101977 --- Fire Sprinkler repairs under permit numbers P17-100634 P17-100444 ---